



Figure 2









Figure 6






Figure S




Figure 9

DD FARTEF THABLE

FiguRE 10




FIGURE 11




Figure 12

PROVIDE AN INPUT DATA CIGNAL, A CLOCK SIGNAL AND A COMPLEMENTARY CLOCK SIGNAL. APPLY THE INPUT DATA TO A FIRST LATCH BY THE CLOCK SIGNAL. THE INPUT DATA TO A SECOND APPLY. LATCH CLOCKED BY THE COMPLEMENTARY SIBNAL. CLOCK THE OUTPUT OF THE FIRST LATCH tO A FIRST XOR GATE AND A THIRD LATCH. APPLY THE OUTPUT OF THE SECOND LATCH TO THE FIRST YOR GATE AND 1352 FOURTH LATCH OUTPUT OF THE THIRD LATCH FOURTH LATCH TO A SECOND YOR GATE. USE THE OUTPUT OF THE FIRST XOR DATE AS AN ERROR SIGNAL, THE OUTPUT OF THE SECOND XOR GATE AS A REFERENCE SIGNAL, THE OUTPUT OF THE THIRD LATCH AS A FIRST DATA OUTPUT, AND THE OUTPUT OF THE FOURTH LATCH AS A SECOND DATH OUTFUT. 1380 SULTRACT THE ERROR SIDNAL FROM 1/2 THE AND FILTER REFERENCE SIGNAL

USE FILTER OUTPUT to ADJUST CLOCK AND COMPLEMENTARY CLOCK SIGNALS